



## Bid Notice Abstract

### Request for Quotation (RFQ)

**Reference Number** 7628895  
**Procuring Entity** DEPARTMENT OF TOURISM - REGION IV  
**Title** DOT 4A REPAIR AND REPLACE OF NISSAN FRONTIER UNDERCHASSIS WITH PLATE NUMBER XMG-781  
**Area of Delivery** Laguna

<b>Solicitation Number:</b>	DOT IV-A-04-2021-020	<b>Status</b>	Active
<b>Trade Agreement:</b>	Implementing Rules and Regulations	<b>Associated Components</b>	1
<b>Procurement Mode:</b>	Negotiated Procurement - Small Value Procurement (Sec. 53.9)	<b>Bid Supplements</b>	0
<b>Classification:</b>	Goods	<b>Document Request List</b>	0
<b>Category:</b>	Vehicle Repair and Maintenance	<b>Date Published</b>	20/04/2021
<b>Approved Budget for the Contract:</b>	PHP 100,000.00	<b>Last Updated / Time</b>	20/04/2021 00:00 AM
<b>Delivery Period:</b>	5 Day/s	<b>Closing Date / Time</b>	23/04/2021 07:00 AM
<b>Client Agency:</b>			
<b>Contact Person:</b>	Jhera Javier San Valentin Administrative Officer IV Brgy. Halang, National Highway Calamba City Laguna Philippines 4027 63-49-5080761 63-49-5080741 dot.calabarzon@gmail.com		

#### Description

BUDGET = PhP 100,000.00 inclusive of tax

#### Includes:

Rep. Tie Rod End Inner & Outer  
 Rep. Idler Arm Assy  
 Rep. Lower Ball Joint Frt. L/R  
 Press in Press out of Lower Ball Joint  
 Rep. Lower Susp. Bushing Frt. L/R  
 Press in Press out of Lower Susp. Bush Frt. L/R  
 Rep. Cross Joint  
 Rep. Shock Absorber Frt. L/R  
 Rep. Shock Absorber Rr L/R  
 Rep. Leap Spring Bush RR L/R  
 Rep Engine Support Frt. L/R  
 Rep Transmission Support  
 Pulldown& Reface Brake Drum RR  
 Rep Brake Shock RR L/R  
 Lubrication of Brake Shoe Adjuster RR L/R  
 Brake Fluid Cleaning Vacuum  
 Flushing and Bleeding with 1 Ltr Brake Fluid  
 Clutch Fluid Cleaning Vacuum Flushing& Bleeding  
 2 pcs Inner Tie Rod End  
 2 pcs Outer Tie Rod End  
 1 pc Idler Arm Asst Frt. L/R

- 2 pcs Lower Ball Joint Frt.
- 2 pcs Lower Susp. Bushing Frt.
- 2 pcs Cross Joint
- 2 pcs Shock Absorber Frt.
- 2 pcs Shock Absorber Rr.
- 8 pcs Leap Spring Bush Rr.
- 2 pcs Engine Support L/R
- 1 pc Transmission Support
- 1 set Brake Shoe RR

**Line Items**

Item No.	Product/Service Name	Description	Quantity	UOM	Budget (PHP)
1	Repair and Maintenance	as indicated in the main document	1	Lot	100,000.00

**Other Information**

- \* The winning bid shall be based on the proposal with the most advantageous package cost, provided that it has met all the financial and technical requirements
- \* The winning bidder must be willing to wait at least 30 working days for government payment facilitation process

**INSTRUCTION TO BIDDERS:**

1. All quotation must be submitted hand carry or courier service to DOT Region IV-A, G/F Dencris Business Center Building, National Highway, Brgy. Halang, Calamba City, Laguna.
2. Proposed bid should be sealed, addressed to BAC Secretariat and indicate the SOLICITATION NUMBER
3. The BAC Secretariat will not ACCEPT proposals/quotations that will be sent through e-mail.

**CHECKLIST OF TECHNICAL & ELIGIBILITY and FINANCIAL REQUIREMENT FOR BIDDERS (GOODS SERVICES):**

1. Mayor's Permit/ Business Permit
2. Philgep's Registration Number
3. Onibus Sworn Statement

**Created by** Jhera Javier San Valentin

**Date Created** 19/04/2021

The PhilGEPS team is not responsible for any typographical errors or misinformation presented in the system. PhilGEPS only displays information provided for by its clients, and any queries regarding the postings should be directed to the contact person/s of the concerned party.

## TERMS OF REFERENCE

I. PROJECT : **Check-up and Repair of Nissan Frontier XMG-781**

II. PROCUREMENT REQUIREMENTS

- Reputable car service center/shop
- Offers warranty
- Willing to provide services on a send-bill arrangement

SCOPE OF WORK/DELIVERABLES


- Check-up and repair of the following:
  - Tie Rod End (inner and outer)
  - Idler Arm Assy
  - Lower Ball Joint Front (Left and Right)
  - Press in Press out of Lower Ball Joint
  - Lower Suspension Bushing Front (Left and Right)
  - Press in Press out of Lower suspension bush Front (Left and Right)
  - Cross Joint
  - Shock Absorber Front (Left and Right)
  - Shock Absorber Rear (Left and Right)
  - Leap Spring Bush Rear (Left and Right)
  - Engine Support Front (Left and Right)
  - Transmission Support
  - Pulldown & reface brake drum rear
  - Brake shoe rear (Left and Right)
  - Lubrication of Brake Shoe Adjuster Rear (Left and Right)
  - Brake Fluid Cleaning Vacuum
  - Flushing and Bleeding with 1 liter Brake Fluid
  - Clutch Fluid Cleaning, Vacuum, Flushing & Bleeding
  
- Replacement of under chassis parts

III. ABC GRAND TOTAL : **Php 100,000.00 inclusive of tax**

IV. PREPARED BY PROJECT OFFICER/CONTACT PERSON:

  
**GINA D. VELASCO**  
Senior TOO/Admin Officer  
T: 049 508-0741

APPROVED BY:

  
**MICHAEL A. PALISPIS**  
Regional Director